

RECEIVED

JAN 17 2002

DIVISION OF  
OIL, GAS AND MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan 2001 To (mo./yr.) Dec 2002
2. DOGM File Number (Mine No): M / 49 / 0006
3. Mine Name: Clinton Mine
4. Mineral(s) Mined (or permitted to mine): Common Clay
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, 1/4, 1/4, Sections 8&9, Township 5S, Range 1W  
1/4, 1/4, 1/4, Section, Township, Range  
1/4, 1/4, 1/4, Section, Township, Range
7. Name of Operator or Company: Interpace Industries, Inc.
8. Permanent Street Address: 736 W Harrisville Rd.  
City, State, Zip: Ogden, UT 84404  
Phone: (801) 782-7933 Fax: (801) 782-5047
9. Company Representative (or designated operator):  
Name: Aaron Hancock  
Title: Director of Mining and Transportation  
Business Address: P.O. Box 12118  
City, State, Zip: Ogden, UT 84412  
Phone: (801) 782-7933 Fax: (801) 782-5047  
☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 19,200 tons

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Clay was mined by trackhoe and stockpiled with dumptruck to stockpile.  
All clay mined was hauled offsite. Unusable material was hauled aside  
and stockpiled. Approx. 320,000 tons of unusable material.

5. How much **additional** acreage was disturbed during the past year? 0
6. How much acreage was **reclaimed** during the past year? 0
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

8. What is the **total** disturbed acreage of entire project at years end? 23.5

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
Will mine approximately the same amount of clay as in 2001.  
Amount of waste material should be substantially less.

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print):

Aaron Hancock

Title of Operator:

Director of Mining and Transportation

Signature of Operator:



Date:

Jan 16, 2002

RECEIVED

JAN 17 2002

DIVISION OF  
OIL, GAS AND MINING



736 HARRISVILLE ROAD, OGDEN, UTAH 84404 801-782-7933

S/43/014  
✓ m/49/006

January 16, 2002

State of Utah  
Department of Natural Resources  
Division of Oil, Gas and Mining  
1594 W North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, UT 84114-5801

Dear Sirs,

Enclosed you will find mining reports for our two clay mines we operate in Henefer and Lehi. Please make note that the legal description of the mine at Henefer has been incorrect for years. The correct description is N.E.  $\frac{1}{4}$  of section 34 T4N R4E. The mine has not moved, but years ago an employee here put the description of another property Interpace owned in Henefer in error on a report.

If you have any questions please feel free to call me at (801)782-7933.

Thanks,

A handwritten signature in blue ink, appearing to read 'A. Hancock', is written over the 'Thanks,' text.

Aaron Hancock  
Director of Mining and Transportation

RECEIVED

JAN 17 2002

DIVISION OF  
OIL, GAS AND MINING